

## **HOTKEY LIST FOR IPUNCH**

### **File Management**

Ctrl-N Open A New File  
Ctrl-O Open an Existing File  
Ctrl-S Save the Current Design  
Ctrl-F4 Close the Current Design  
Ctrl-P Print Normal

### **Toolbar/Dialog Box Access**

Ctrl-Q Close Program  
Alt-F4 Close Program  
Ctrl-W Show Whole View Pad  
Alt-C Compact Design Color  
Ctrl-T Statistics  
Ctrl-M Settings Manager  
Ctrl-F Machine Code Filter Editor  
F3 Help About

### **Image / Canvas Manipulation**

Ctrl-U Acquire Image from Scanner  
Alt-Enter Change Canvas/File Size  
F11 Fade/Lighten Image  
F12 Fade/Darken Image

### **Selection**

Ctrl-A Select All  
Ctrl-click Toggle Selection  
Shift-click Cumulative Selection  
Ctrl-click Region Select  
Hold Shift Additive Selection

### **General Punching**

F4 Change Curve/Line Mode  
Ctrl-G Go To Punching  
Alt-M Manual Stitch Mode  
Alt-J Jump Stitch Mode  
F2 Toggle vertical/horizontal axis-  
freeze/ free float mode control for  
cursor movement  
Alt-L Modify Guide Line

Ctrl-C Copy selected object/stitch group(s)  
Ctrl-X Cut selected object/stitch group(s)  
Ctrl-V Paste selected object/stitch  
Group(s)  
Ctrl-Z Undo  
Ctrl-Y Redo  
Del Delete selection  
ESC Exit function & Default to  
Selection Mode  
Enter Next Step

### **Block Editing**

Alt-X X-Mirror  
Alt-Y Y-Mirror

### **Condensed Editing**

Alt-S Change Settings of selected stitch  
Group  
Alt-T Change Stitch Size/Count of  
selected stitch group  
Alt-U Change Stitch Type

### **Zoom / Pan**

+ Zoom In  
- Zoom Out  
arrow keys Pan  
Hold Space Bar Grab & Drag  
Canvas  
Alt-D Actual Size

### **Navigation & Viewing**

Pg Up/Dn Stitch Group Navigation  
Alt-W Highlight Selected  
Stitch Groups  
Alt-G Grid On/Off  
F10 Simulation display