

HOTKEY LIST FOR IPUNCH

GENERAL DIGITIZING SHORTCUTS

While Using the Polyline Tool:

F4 Change Curve/Line Mode
Ctrl Locks cursor movement to vertical horizontal or 45 degrees

General

Enter Enters stitch generation Mode (objects must be selected) or Go to next step in stitch generation process
Alt-M Manual Stitch Mode
Alt-J Jump Stitch Mode
F2 Toggle cursor movement between vertical/horizontal/free-float modes
Alt-L Modify Guide Line
Ctrl-C Copy selected object/stitch group(s)
Ctrl-X Cut selected object/stitch group(s)
Ctrl-V Paste selected object/stitch Group(s)
Ctrl-Z Undo
Ctrl-Y Redo
Del Delete selection
ESC Exit current function & default to Selection Mode

EDITING SHORTCUTS

Block Editing

Alt-X X-Mirror
Alt-Y Y-Mirror

Condensed Editing (processing) modes

Alt-S Change Stitch Settings
Alt-T Change Stitch Size/Count
Alt-U Change Stitch Type

SELECTION SHORTCUTS

Ctrl-A Select All
Ctrl-click Toggle Selection
Shift-click Cumulative Selection
Ctrl-click Region/Marquee Selection
Hold Shift Additive Selection

NAVIGATION & VIEWING SHORTCUTS

Pg Up/Dn Stitch Group Navigation
Alt-W Highlight selected stitch groups
Alt-G Toggle grid on/off
F10 Simulation display

Zooming / Panning

+ Zoom In
- Zoom Out
Arrow Keys Pan
Spacebar Grab & drag canvas
Alt-D Jump to/from 100% magnification

Image/Canvas Manipulation

Ctrl-U Acquire Image from Scanner
Alt-Enter Change Canvas/File Size
F11 Fade/Lighten Image
F12 Fade/Darken Image

FILE MANAGEMENT SHORTCUTS

Ctrl-N Open A New File
Ctrl-O Open an Existing File
Ctrl-S Save the Current Design
Ctrl-F4 Close the Current Design
Ctrl-P Print Normal

TOOLBAR / DIALOG BOX ACCESS

Ctrl-Q Close Program
Alt-F4 Close Program
Ctrl-W Show Whole View Pad
Alt-C Compact Design Color
Ctrl-T Statistics
Ctrl-M Settings Manager
Ctrl-F Machine Code Filter Editor
F3 Help About